

# Libero SoC v11.9 SP2

## Release Notes

01/2019



---

a  **MICROCHIP** company

a  MICROCHIP company**Microsemi Corporate Headquarters**One Enterprise, Aliso Viejo,  
CA 92656 USA

Within the USA: +1 (800) 713-4113

Outside the USA: +1 (949) 380-6100

Fax: +1 (949) 215-4996

Email: [sales.support@microsemi.com](mailto:sales.support@microsemi.com)[www.microsemi.com](http://www.microsemi.com)

©2018 Microsemi Corporation. All rights reserved. Microsemi and the Microsemi logo are registered trademarks of Microsemi Corporation. All other trademarks and service marks are the property of their respective owners.

Microsemi makes no warranty, representation, or guarantee regarding the information contained herein or the suitability of its products and services for any particular purpose, nor does Microsemi assume any liability whatsoever arising out of the application or use of any product or circuit. The products sold hereunder and any other products sold by Microsemi have been subject to limited testing and should not be used in conjunction with mission-critical equipment or applications. Any performance specifications are believed to be reliable but are not verified, and Buyer must conduct and complete all performance and other testing of the products, alone and together with, or installed in, any end-products. Buyer shall not rely on any data and performance specifications or parameters provided by Microsemi. It is the Buyer's responsibility to independently determine suitability of any products and to test and verify the same. The information provided by Microsemi hereunder is provided "as is, where is" and with all faults, and the entire risk associated with such information is entirely with the Buyer. Microsemi does not grant, explicitly or implicitly, to any party any patent rights, licenses, or any other IP rights, whether with regard to such information itself or anything described by such information. Information provided in this document is proprietary to Microsemi, and Microsemi reserves the right to make any changes to the information in this document or to any products and services at any time without notice.

**About Microsemi**

Microsemi Corporation (Nasdaq: MSCC) offers a comprehensive portfolio of semiconductor and system solutions for aerospace & defense, communications, data center and industrial markets. Products include high-performance and radiation-hardened analog mixed-signal integrated circuits, FPGAs, SoCs and ASICs; power management products; timing and synchronization devices and precise time solutions, setting the world's standard for time; voice processing devices; RF solutions; discrete components; enterprise storage and communication solutions; security technologies and scalable anti-tamper products; Ethernet solutions; Power-over-Ethernet ICs and midspans; as well as custom design capabilities and services. Microsemi is headquartered in Aliso Viejo, California, and has approximately 4,800 employees globally. Learn more at [www.microsemi.com](http://www.microsemi.com).

51300212-1/01.19

---

## Revision History

---

The revision history describes the changes that were implemented in the document. The changes are listed by revision, starting with the most current publication.

### **Revision 1.1**

Added known issue 3.1 SmartTime: False failure during max/best case analysis.

### **Revision 1.0**

Revision 1.0 was the first publication of this document.

---

## Contents

---

Revision History.....	3
Revision 1.1.....	3
Revision 1.0.....	3
1 Libero SoC v11.9 SP2 Release Notes .....	5
2 What’s New in Libero SoC v11.9 SP2 .....	6
2.1 ECC Flags on Depth Cascaded RAM Blocks .....	6
2.2 Double accounting of clock latency when applied to generated clocks .....	6
2.3 Timing arc dropped when using interface logic LUT with inversion .....	7
2.4 Zero delay on hardwired nets from specific IOs to GRESET .....	7
3 Known Limitations, Issues and Workarounds .....	8
3.1 SmartTime: False failure during max/best case analysis .....	8
4 System Requirements .....	9
4.1 Operating System Support .....	9
5 Libero SoC v11.9 SP2 Download .....	10
5.1 Downloading SoftConsole 3.4/4.0/5.1 .....	10

---

## 1 Libero SoC v11.9 SP2 Release Notes

---

The Libero® system on chip (SoC) v11.9 SP2 is a service pack release of the Libero SoC v11.9 software for designing with Microsemi's power efficient flash [FPGAs](#), [SoC FPGAs](#), and [rad-tolerant FPGAs](#). The suite integrates industry standard Synopsys [Synplify Pro](#)® synthesis and Mentor Graphics [ModelSim](#)® simulation with best-in-class constraints management, debug capabilities, and secure production programming support.

Use Libero SoC v11.9 SP2 for designing with Microsemi's [RTG4](#) Rad-Tolerant FPGAs.

To access datasheets, silicon user guides, tutorials, and application notes, visit [www.microsemi.com](http://www.microsemi.com), navigate to the relevant product family page, and click the **Documentation** tab. [Development Kits & Boards](#) are listed in the **Design Resources** tab.

**Libero SoC v11.9 SP2 implements several critical bug fixes focusing on the RTG4 FPGA family. This release is only intended for use with the RTG4 family. It is recommended that all Libero projects targeting the RTG4 family be opened with this release, and timing reports regenerated.**

## 2 What's New in Liberio SoC v11.9 SP2

Liberio SoC v11.9 SP2 implements the following bug fixes targeted to the RTG4 family:

### 2.1 ECC Flags on Depth Cascaded RAM Blocks

Liberio SoC v11.9 introduced features in the Dual-port LSRAM, Two-port LSRAM and uSRAM configurators to generate logic that gates-off the ECC flags for inactive RAM blocks. The gating logic was correctly generated up to the cascading depths listed below, depending on the optimization option of High-speed or Low-power.

- Two-port LSRAM Low-power 4K x 36
- Dual-port LSRAM 8K x 18
- uSRAM 256 x 18

However, due to the depth limits on the RAM configurators, any RAM components built with a cascading depth greater than 8 RAM blocks deep did not include sufficient logic to ensure the correct RAM block's ECC flags reached the component-level flag output ports.

The ECC flags from the active RAM blocks beyond the above depth limits would be in the 'X' state in pre-synthesis simulations and the '0' state in post-synthesis and post-layout simulations.

Furthermore, synthesis with Synplify Pro will generate warnings such as those shown below:

```
@W: CG360 : "C:\...\TPLSRAM_10213x72_0_RTG4TPSRAM.v":334:8:334:21|Removing wire
BLKY2_pipe[2], as there is no assignment to it.
```

```
@W: CL156 : "C:\...\TPLSRAM_10213x72_0_RTG4TPSRAM.v":334:8:334:21|*Input BLKY2_pipe[2] to
expression [instance] has undriven bits; assigning undriven bits to 0. Simulation
mismatch possible. Assign all bits of the input.
```

Liberio SoC v11.9 SP2 lifts the depth limits, enabling the Dual-port LSRAM, Two-port LSRAM and uSRAM configurators to correctly generate logic that gates-off ECC flags for inactive RAM blocks for all depths.

Each RAM component generated by the Dual-port LSRAM, Two-port LSRAM and uSRAM configurators includes a log file within the project's /component/work/<component\_name>/<instance\_name>/ sub-folder listing the RAM cascade configuration. The number of blocks cascaded depth-wise can be used to determine whether the particular RAM component uses more than 8 RAM blocks deep, and requires regeneration using Liberio SOC v11.9 SP2.

```
Cascade Configuration:
  Write Port configuration   : 1024x18
  Read Port configuration   : 1024x18
  Number of blocks depth wise: 10
  Number of blocks width wise: 4
```

Update the RAM components within a design by regenerating them using Liberio SoC v11.9 SP2.

### 2.2 Double accounting of clock latency when applied to generated clocks

When a clock latency constraint is set on a generated clock, the Static Timing Analyzer uses the late clock latency (and respectively early clock latency) value in the calculation of the data arrival time (and respectively the data required time). However, due to an error introduced in Liberio SoC v11.7.SP1, an additional delay (equal to late-early) is incorrectly added to the clock net driven by the clock source in the required time calculation.

This issue is fixed in the Liberio SoC v11.9 SP2 release.

### **2.3 Timing arc dropped when using interface logic LUT with inversion**

In the specific scenario of a Flip-Flop connected directly to the physical D pin of a neighboring interface logic combinatorial cell with an inversion of the signal, the timing model of the interface logic comb cell was missing the timing arc from the D pin to the Y pin. This rare error prevents the static timing analyzer from accounting for the paths that go through this connection when checking for timing violations.

This issue is fixed in the Libero SoC v11.9 SP2 release.

### **2.4 Zero delay on hardwired nets from specific IOs to GRESET**

IO to GRESET hardwired nets at four specific GRESET input pin locations have zero delay value due to a pin name mismatch with the database. Consequently, the insertion delay on the GRESET is underestimated.

This issue is fixed in the Libero SoC v11.9 SP2 release.

---

## 3 Known Limitations, Issues and Workarounds

---

Known issues from Libero SoC v11.9 also apply to Libero SoC v11.9 SP2. Review the [Libero SoC v11.9 Release Notes](#) for Known Issues in Libero SoC v11.9.

### 3.1 SmartTime: False failure during max/best case analysis

Verify timing may fail during fast corner analysis.

**Workaround:** Disable Coverage report (Verify Timing>Configure Options) or upgrade to Libero SoC v12.0.



---

## 4 System Requirements

---

For information about operating system support and minimum system requirements, see the [System Requirements](#) web page.

For Linux OS setup instructions, see [How to Set Up Linux Environment for Libero User Guide](#):

### 4.1 Operating System Support

#### Supported

- Windows 7, Windows 8.1, Windows 10
- RHEL 5\*, RHEL 6, RHEL 7, CentOS 5\*, CentOS 6, and CentOS 7
- SuSE 11 SP4 (Libero only. FlashPro Express, SmartDebug, and Job Manager are not supported.)

**Note:** \* RHEL 5 and CentOS 5 do not support programming using FlashPro5.

#### Not Supported

- 32-bit operating systems
- Windows XP
- Support for the following operating systems will cease with the next major Libero SoC release. For more information, refer to [PCN17031](#).
  - RedHat Enterprise Linux 5.x through 6.5
  - CentOS 5.x through 6.5

---

## 5 Liberio SoC v11.9 SP2 Download

---

Click the following links to download Liberio SoC v11.9 SP2 on Windows and Linux operating systems:

- [Windows Download](#)
- [Linux Download](#)
- [Mega Vault Download](#)

(Note: There are no changes in the Mega Vault for Liberio SoC v11.9 SP2; use the Liberio SoC v11.9 Mega Vault for this release as well.)

**Note:** Installation requires administrator privileges to the system.

Liberio SoC v11.9 SP2 is an incremental service pack and can be installed over Liberio SoC v11.9, or over Liberio SoC v11.9 SP1

After successful installation, clicking **Help-> About Liberio** will show Version: 11.9.2.1.

### 5.1 Downloading SoftConsole 3.4/4.0/5.1

Liberio SoC v11.9 SP2 is compatible with SoftConsole v3.4 SP1, SoftConsole v4.0 and SoftConsole v5.x

- [SoftConsole Download](#)